

### General Men's Sizing Chart

Size	Small	Medium	Large	X-Large	2X-Large
Front Body Length	29	30	31	32	33
Chest 1" Below Armpit Circumference	42	45	48	50	52
Bottom Relaxed Circumference	42	45	48	50	52